



Prerequisites for Quality Control Inspector Certification

All items below are required prior to taking the written and/or field certification exams:

You must obtain a minimum of **40 points** from any combination of activities below:

- Industry inspector specific experience (site visits, inspections, diagnostics, etc); **maximum of 20 points**
 - **10 points** for 1,000 hours
- Other industry specific experience (crew leader / energy auditor) minimum 2,000 hours in either activity
 - **5 points** for crew leader
 - **10 points** for energy auditor completing a minimum of 15 audits (proof required)
- Building experience (framing, roofing, drywall, siding, etc); **maximum of 10 points**
 - **5 points** for each 1,000 hours
- Training from industry specific training center (training whose content can be matched against and lines up with the content of the job task analysis for the certification); **maximum of 10 points**
 - **5 points** for every 40 hours
- Industry certifications (RESNET, BPI, NATE, EPA). Other certifications also considered; **maximum of 10 points**
 - **5 points** per certification

Revised: 8/30/2013